

04. Dez. 2012

Continental Automotive GmbH P.O.Box 10 09 43 93009 Regensburg

Analog Devices
To Mr. Eckl
Wilhelm-Wagenfeld-Str. 6
80807 München

EINGEGANGEN
Name Rolf Juers
Department CEP RBG SQM M E
Plant Regensburg
Tel. +49(941)7904120
Fax +49(941)790994120
E-Mail rolf.juers@continental-corporation.com
NonConf. Rep. 200117007
Date 04.12.2012
Original printed on

Non Conformance Report 200117007 / Plant 1000

Priority Level:
Priority

Designation
SEN/CISS/ADXL950,70g acc + 50gavg sound
Supplier product no.

Supplier ID
8329304

Material No. Rev.
A2C00043643

Ordering No.

Incoming date
03.12.2012

Inspection Lot
0

Delivery qty.
1

RMA(returned material authorization)

Quantity of failed components
1

Notification No. Pos.	Failure Description	Failure qty.
200116995 1	<p>Origin: CC warranty (SQA) for Analysis Rear Crash entered; CISS sensor x-output is not stable at low temperature; several peaks during cooling inside the temp. chamber; see attached sheets; sensor was testet with Mr. Panse (AD); sensor was taken directly by Mr. Panse</p>	1

Continental Automotive GmbH
Managing Directors: Georg Sistermanns, Harald Stuhlmann
Registered Office: Hannover
Commercial Registry: Hannover, HRB 59424

Postal Address:
Continental Automotive GmbH
CEP RBG SQM M E
P.O. Box
93009 Regensburg

Office Address:
Siemensstr. 12
93055 Regensburg
Tel. +49(0)941/790-02

Continental Automotive GmbH
Managing Directors: Georg Sistermanns, Harald Stuhlmann
Registered Office: Hannover
Commercial Registry: Hannover, HRB 59424

at Conti^o
with Martin Pardo

Supply Voltage
3,308V

X-out	selftest	change	-90	+90
1,710 - 1,723	2,155 - 2,168	0,432 - 0,458	1,696 - 1,711	1,729 - 1,745

1,68 2,11 0,43 1,67 1,7 03.12.2012

HF-out	selftest	change
0,329	0,825	0,496

03.12.2012

Erled.

04. Dez. 2012

EINGEGANGEN