

I am FAE in Japanese distributor.
Our customer evaluate ADM2682E and found unnecessary "L" output.
Please see figure1, Figure2 and Figure3.
Could you tell me why RXD output unnecessary "L" ?




Figure1




Figure2




Figure3